# GEOTECHNICAL SUBSURFACE INVESTIGATION REPORT

# Montgomery County Task Order #13 Subtask B Phase III (Franklin Knolls) Montgomery County, Maryland



### PREPARED FOR:

McCormick Taylor 509 South Exeter Street, 4th Floor Baltimore, Maryland 21202

### **PREPARED BY:**



Ph: (301) 306-3091 Fax: (301) 306-3092 www.abconsultantsinc.com

Surveyors Contractors

January 15, 2013

Attn: Ms. Kimi Schmidt McCormick Taylor 509 South Exeter Street, 4th Floor Baltimore, Maryland 21202

REF: Report of Subsurface Investigation and Studies Montgomery County Task Order #13 Subtask B Phase III, Roadway LID - Franklin Knolls Montgomery County, Maryland AB Job No. 10-368.01

Dear Ms. Schmidt:

AB Consultants, Inc. (ABC) is pleased to submit this soil report containing the results of geotechnical investigation for the above referenced site. To obtain information of the subsurface condition, a total of twenty-two (22) 10-ft deep soil borings and infiltration tests were planned to be drilled and performed. The purpose of this study was to explore the subsurface conditions of this storm water management (SWM) improvement project. The following report sections discuss the results of field and laboratory studies, design recommendations and construction methods for the proposed structures.

All samples obtained from soil test borings will be retained in our laboratory for a period of thirty (30) days from the date of this report. They will be available for inspection during this period. After that time, the samples will be discarded.

It has been a pleasure serving you on this project. If you have any questions regarding this report, or if we can be of further service in any way, please contact us.

Very truly yours,

AB Consultants, Inc.

Sattprakash Patel Staff Engineer Kim-Hou Chan, P.E Geotechnical & Field Ser

## TABLE OF CONTENT

1.0	INT	RODUCTION	. 2
	1.1	GENERAL	.2
	1.2	SCOPE OF WORK	.2
	1.3	SITE LOCATION	.2
2.0	FIE	LD ACTIVITIES AND SUBSURFACE EXPLORATION	. 2
	2.1	SOIL BORINGS	.2
	2.2	SUBSURFACE INVESTIGATION	.3
	2.3	On-site Infiltration Test and Results	.3
3.0	LAE	BORATORY TESTING PROGRAM	. 4
	3.1	LABORATORY TESTING	.4
4.0	GE	NERAL SITE AND SUBSURFACE CONDITIONS	.5
	4.1	SITE CONDITION	.5
	4.2	SITE GEOLOGY	.5
	4.3	SUBSURFACE SOIL CONDITION	.5
	4.4	GROUNDWATER OBSERVATIONS	.6
5.0	AN	ALYSIS AND RECOMMENDATIONS	.6
	5.1	SWM FACILITY CONSIDERATIONS	.6
6.0	SIT	E GRADING AND CONSTRUCTION CONSIDERATIONS	.8
	6.1	SITE GRADING	.8
	6.2	SUITABLE FILL MATERIAL	.9
	6.3	COMPACTION REQUIREMENT	.9
7.0		NSTRUCTION CONSIDERATIONS	
8.0	GEI	NERAL COMMENTS	10

### **APPENDICES** A. General Notes

- B. Vicinity Map
  C. Boring Plan
  D. Boring Logs
  E. Lab Test Results
- F. Field Infiltration Test Results

#### 1.0 INTRODUCTION

#### 1.1 General

This report summarizes the findings from subsurface soil investigations conducted by ABC for the storm water management (SWM) improvement project located in Montgomery County, Maryland. Per information provide to us, multiple Low Impact Design SWM facilities are proposed on various streets in Montgomery County, Maryland. The objective was accomplished by conducting field and laboratory tests. The results of these tests constitute the bases for determining pertinent design parameters for the proposed improvement. This study was conducted for McCormick Taylor and has been performed in general accordance with our letter proposal dated on December 2010 and subsequent conversations.

# 1.2 Scope of Work

The investigation of existing subsurface soil conditions at the site consisted of the following:

- Planning and executing subsurface exploration programs to evaluate soil and ground conditions for SWM improvements.
- Conducting on-site infiltration tests.
- Performing laboratory tests on soil samples obtained from the borings.
- Providing geotechnical report that includes results of field and laboratory studies.

### 1.3 Site Location

The field study was performed at various streets in the subdivision of Franklin Knolls, Montgomery County, Maryland. Soil borings and infiltration test holes are located on Weaver Street, Malibu Street, Gregorio Drive, Lowander Lane, Whitaker Terrace, Greer Avenue, Melbourne Avenue, and Curran Road.

#### 2.0 FIELD ACTIVITIES AND SUBSURFACE EXPLORATION

### 2.1 <u>Soil Borings</u>

A total of twenty-two (22) soil borings were drilled for subsurface study on this project site. Borings were drilled at the referenced site to depths of 10-ft below the existing ground surface on November 20 and 30, 2012.and December 3 and 4, 2012. Soil

borings were staked out in the field by ABC. Site locations and boring plans are included in the Appendix.

# 2.2 <u>Subsurface Investigation</u>

Borings were drilled using truck mounted drill rig, B-61. Test borings were advanced by using hollow-stem augers and soil samples were obtained using the Standard Penetration Tests (SPT) in accordance with ASTM D1586. SPT samples were obtained for each boring at depth intervals of every 2.5 feet. Due to overhead power lines, continuous flight auger drilling method was used to collect samples. A representative portion of each split spoon sample was placed in a glass jar and was transported to our laboratory.

In the split-barrel sampling procedure, a 2.0-inch O.D. split-barrel sampling spoon is driven into the ground with a 140-pound hammer, free falling a distance of 30 inches. The blows required to advance the sampling spoon to a specified distance are reported as the penetration resistance values. The values are shown on boring logs at the depths of their occurrence. The N-value is the sum of standard penetration resistance values that advanced through the last 12-inches of sampling. The N-value is an indication of the relative density of in-place granular soils and, to a lesser degree of accuracy, the consistency of cohesive soils.

Groundwater level was monitored in the boring. Samples obtained from the boring were inspected by a geotechnical engineer and the field logs were edited accordingly. The final logs that indicate the subsurface conditions encountered are included in the Appendix.

## 2.3 On-site Infiltration Test and Results

Twenty two (22) infiltration tests were performed in auger borings drilled at a 5-ft offset from the soil sample boring. Test holes were drilled with 8-inch diameter auger to a depth of 5.5-ft below existing ground. 5-inch diameter solid PVC casings were inserted and water was then introduced for an overnight presoak period. Infiltration tests were performed the next day by refilling PVC casings with water to the presoak level and then monitoring water levels for one hour time. Repeat this procedure (refilling the casing each time) three additional times, for a total of four observations. Field in-situ infiltration test data are included in the Appendix and results are summarized in following table.

SUMMARY OF IN-SITU INFILTRATION TEST RESULTS											
Boring No.	Test Hole Depth	Existing Elevation	Sample Description at Bottom of Test Hole	Suggested Average Infiltration Rate (in./hr)							
B-51	5.5	283.5	Silty fine sand	1.7							
B-52	5.5	258.5	Silty fine sand	0.2*							
B-53	5.5	240.5	Silty fine sand	0.5							
B-54	5.5	237	Silty fine sand	1.2							
B-55	5.5	259.5	Silty fine sand	0.4*							
B-56	5.5	266	Silty fine sand	0.6							
B-57	5.5	268.5	Silty fine sand	1.2							
B-58	5.5	271	Silty fine sand	1.2							
B-59	5.5	273	Silty fine sand	1.1							
B-60	5.5	263.5	Silty fine sand	1.0							
B-61	5.5	270	Silty fine sand	2.7							
B-62	5.5	296.5	Silty fine sand	1.1							
B-63	5.5	303	Silty fine sand	0.3*							
B-64	5.5	277.5	Silty fine sand	1.9							
B-65	5.5	285.5	Silty fine sand	1.8							
B-66	5.5	299.5	Silty fine sand	1.0							
B-67	5.5	307	Silty fine sand	1.6							
B-68	5.5	307.5	Silty fine sand	1.4							
B-69	5.5	297.5	Silty fine sand	1.2							
B-70	5.5	290.5	Silty fine sand	0.6							
B-71	5.5	292.5	Silty fine sand	1.7							
B-72	5.5	300	Silty fine sand	1.5							

<sup>\*</sup> Low infiltration rates were recorded. It may be the result of dense soil stratum below infiltration holes.

## 3.0 LABORATORY TESTING PROGRAM

# 3.1 <u>Laboratory Testing</u>

Laboratory tests were performed on selected representative samples. Natural moisture contents were performed on all soil samples, and results are included in boring logs. Atterberg limits and sieve analysis were conducted on selected samples. Atterberg limits results are shown in boring logs in correspondence with the sample depths and results of sieve analyses are presented in the Appendix.

#### 4.0 GENERAL SITE AND SUBSURFACE CONDITIONS

### 4.1 <u>Site Condition</u>

The SWM facilities are proposed on various streets in the Franklin Knolls Subdivision in Silver Spring, Maryland. Borings on this project site are located in the single-home residential areas. Utilities in the vicinity of boring holes include underground water, sewer, gas, cable and overhead power.

## 4.2 <u>Site Geology</u>

Geologically, the project site is in the Boulder Gneiss of the Eastern Piedmont Metasedimentary Rocks Series of the Piedmont Plateau Province, which is composed of thick-bedded to massive, pebble- and boulder-bearing, arenaceous to pelitic metamorphic rock, typically a medium-grained, garnet-oligoclase-mica-quartz gneiss; locally an intensely foliated gneiss or schist.

## 4.3 Subsurface Soil Condition

Various soil types were grouped into the major zones noted on the boring logs. A brief explanation of the terms and notes used in the logs is included with this report. The stratification lines designating the interfaces between earth materials on the boring logs are approximate; in situ, the transitions may be gradual. Detailed soil description and depth of various soil strata are given in boring logs, together with SPT blow counts with depth. In general, the encountered soils are grouped and summarized as follows:

Topsoil: Topsoil was encountered in all boring. Topsoil is defined as the more highorganic, weathered surficial soils horizon capable of supporting vegetation.

Type A Silty Fine Sand: Below the Topsoil, reddish brown to brown and gray sandy soil with mica and trace of rock fragments was encountered in most of borings and extended to completion depth of borings. N-values in this layer were ranging from 4 to more than 50 blows per foot. Due to the presence of rock fragments, higher blow counts were recorded in few boreholes at various depths.

Type B Silty Clay: Reddish brown low plasticity clayey soil was encountered in boring B-67 at depth of 6 ft below Type A Soil and extended to completion depth of boring. N-values in these soils were ranging from 4 to 10 blows per foot.

### 4.4 Groundwater Observations

Groundwater observations were made in every borehole during drilling, and after completion of drilling operations. As noted on boring logs, groundwater was **not encountered** in all borings during drilling and after drilling. Water level observations are presented at the lower left hand corner of boring logs. Fluctuations in the level and quantity of ground water will occur due to variations in rainfall, temperature, soil permeability and other factors not evident at the time of the water level measurements recorded on boring logs.

## 5.0 ANALYSIS AND RECOMMENDATIONS

## 5.1 SWM Facility Considerations

The infiltration design criteria established by the Maryland Department of the Environment (MDE) Water Management Administration advises that infiltration practices are not recommended to be utilized: (a) in regions where the bottom of the infiltration facility is in existing or newly placed fill, or (b) in materials that exhibit an infiltration rates less than 0.52 inches per hour, or (c) where the groundwater table or bedrock is within 4 feet of the bottom of the infiltration facility.

Proposed plan or structural detail of the proposed SWM facilities were not provided by the date of this report. Per the information provided from McCormick Taylor, Inc., infiltration structures are considered in this SWM improvement project. Based on information revealed from borings, laboratory test results, and our visual classification of the recovered soil samples, the encountered subsoils are classified per the USDA classification system and a summary is presented in the following table.

SUMMARY OF SOIL PROPERTIES PER USDA CLASSIFICATION											
Boring No.	Sample Depth (ft)	USDA Textural Classification	Minimum Infiltration Rate (in/hr)	Hydrologic Soil Grouping							
B-51	0.5 to 10	Sandy loam	1.02	A							
B-52	0.5 to 10	Sandy loam	1.02	A							
B-53	0.5 to 10	Sandy loam	1.02	A							
B-54	0.5 to10	Sandy loam	1.02	A							
B-55	0.5 to 10	Sandy loam	1.02	A							
B-56	0.5 to 10	Sandy loam	1.02	A							
B-57	0.5 to 10	Sandy loam	1.02	A							
B-58	0.5 to10	Loamy sand	2.41	A							
B-59	0.5 to 10	Sandy loam	1.02	A							
B-60	0.5 to 10	Loamy sand	2.41	A							
B-61	0.5 to 10	Loamy sand	2.41	A							
B-62	0.5 to 10	Loamy sand	2.41	A							
B-63	0.5 to 10	Sandy loam	1.02	A							
B-64	0.5 to 10	Loamy sand	2.41	A							
B-65	0.5 to 10	Loamy sand	2.41	A							
B-66	0.5 to 10	Loamy sand	2.41	A							
B-67	0.5 to 6	Sandy loam	1.02	A							
D-07	6 to 10	Silty clay	0.04	D							
B-68	0.5 to 10	Loamy sand	2.41	A							
B-69	0.5 to 10	Loamy sand	2.41	A							
B-70	0.5 to 10	Sandy loam	1.02	A							
B-71	0.5 to 10	Loamy sand	2.41	A							
B-72	0.5 to 10	Loamy sand	2.41	A							

Considering the USDA classification, boring information, on-site infiltration tests and groundwater observation, most of the proposed SWM areas are considered suitable for infiltration design in accordance with general design criteria. Results of our findings are summarized in the following table.

SUMMARY OF SWM CONSIDERATIONS AT 2.5- to 6-ft BELOW GROUND												
Boring No.	Existing Elevation	Facility Bottom Elevation	On-site Infiltration Rate (in/hr)	Infiltration Rate per USDA (in/hr)	Infiltration SWM Facility							
B-51	283.5	278	1.7	1.02	Acceptable							
B-52	258.5	253	0.2*	1.02	Not Acceptable							
B-53	240.5	235	0.5	1.02	Acceptable							
B-54	237	231.5	1.2	1.02	Acceptable							
B-55	259.5	254	0.4*	1.02	Not Acceptable							
B-56	266	260.5	0.6	1.02	Acceptable							
B-57	268.5	263	1.2	1.02	Acceptable							
B-58	271	265.5	1.2	2.41	Acceptable							
B-59	273	267.5	1.1	1.02	Acceptable							
B-60	263.5	258	1.0	2.41	Acceptable							
B-61	270	264.5	2.7	2.41	Acceptable							
B-62	296.5	291	1.1	2.41	Acceptable							
B-63	303	297.5	0.3*	1.02	Not-Acceptable							
B-64	277.5	272	1.9	2.41	Acceptable							
B-65	285.5	280	1.8	2.41	Acceptable							
B-66	299.5	294	1.0	2.41	Acceptable							
B-67	307	301.5	1.6	1.02	Acceptable							
B-68	307.5	.302	1.4	0.04	Acceptable							
B-69	297.5	292	1.2	2.41	Acceptable							
B-70	290.5	285	0.6	2.41	Acceptable							
B-71	292.5	287	1.7	1.02	Acceptable							
B-72	300	294.5	1.5	2.41	Acceptable							

<sup>\*</sup> Low infiltration rates were recorded. It may be the result of dense soil stratum.

It is recommended that during construction of the SWM facility, the soil encountered at and below the planned elevation, to be verified along with their infiltration characteristics.

# 6.0 SITE GRADING AND CONSTRUCTION CONSIDERATIONS

## 6.1 Site Grading

Grading preparation should include clearing within the limits of construction, grubbing and removal of the organic surficial soils. The potential thickness of material subject to stripping will vary from zero inches to six (6) inches. Design and construction

should include provisions for temporary storage, hauling, and disposal of stripped materials at an approved off-site location.

Following stripping, cutting, the subgrade should be verified prior to the installation of SWM structures. Areas identified during the verification process as soft or exhibiting "pumping" tendencies should be undercut, processed and recompacted or removed and replaced with suitable fill, whichever is appropriate.

## 6.2 <u>Suitable Fill Material</u>

Fill and backfill for general areas should be free of organics and debris and rock fragments in excess of 3-in. in any dimension. In the upper 18 inches of fill, maximum particle size should be limited to about 1.5 inches. As per ASTM D2478 classification, imported select fill should consist of sandy gravel (GM), clayey gravel (GC), gravelly sand (SP), silty sand (SM), clayey sand (SC), or low-plasticity sandy clay (CL) with a liquid limit and plasticity index of less than 40 and 15 respectively, or an approved alternate.

## 6.3 <u>Compaction Requirement</u>

Fill soils should be compacted to a minimum of 95 percent of maximum Standard Proctor dry density (ASTM D698), with a moisture content range of minus to plus 2 percent of optimum. Fill should be placed in a nominal 10-inch-thick loose lifts. Each lift of fill should be properly compacted, tested and approved prior to placing subsequent lifts.

#### 7.0 CONSTRUCTION CONSIDERATIONS

Positive surface drainage should be established at the start of work, be maintained during construction and following completion of the project to prevent surface water ponding and subsequent saturation of subgrade soils. Prolonged exposure or saturation of subgrade soils by ponding or runoff water may result in significant changes in strength and compressibility characteristics. Saturated subgrade soils should be excavated and replaced with suitable materials.


Depending upon weather conditions during and prior to construction, groundwater may be encountered in the excavation areas. Any seepage into the construction

excavation could be controlled by pumping from sump pits. During site preparation, surface runoff should be directed away from the construction areas.

## 8.0 GENERAL COMMENTS

The soil classifications presented in this report are based upon the data obtained from the soil borings performed at indicated locations and from any other information discussed in this report. This report does not reflect any variations that may occur across the site. The nature and extent of such variations may not become evident until construction. If variations appear evident, the conclusion and recommendations of this report should then be reviewed by ABC geotechnical engineer in light of the new information.

This report has been prepared for the exclusive use of our client for specific application to the project discussed and has been prepared in accordance with generally accepted geotechnical engineering practices. No other warranties, either expressed or implied, are intended or made. In the event that any changes in the nature, design or location of the project as outlined in this report are planned, the conclusions and recommendations contained in this report shall not be considered valid unless the changes are reviewed and the conclusions of this report modified or verified in writing by ABC geotechnical engineer of record.



# **GENERAL NOTES**

## **Drilling and Sampling Symbols**



N = Standard penetration, blows per foot of a 140 lbs hammer for 30" drop

RQD = Rock Quality Designation

LL = Liquid Limit PL = Plastic Limit PI = Plasticity Index

#### **Cohesionless Soils**

If the sand or silt content of a soil is great enough, the soil becomes non-cohesive or semi-cohesive. The soil classification becomes SAND or SILT with the other soil constituents being modifying.

#### Based on N-Value

10 to 29 Blows......Medium Dense

#### **Cohesive Soils**

If clay content is sufficient so that clay dominates soil properties, then CLAY becomes the major soil constituent as modifier. Other minor soil constituents may be added according to classification breakdown for cohesion less soils: i.e. silty clay, trace of some sand, trace of gravel.

#### Based on N-Value

#### Based on Penetrometer Value

 Below 0.25
 Very Soft
 1.00 to 1.99
 Stiff

 0.25 to 0.49
 Soft
 2.00 to 3.99
 Very Stiff


 0.50 to 0.99
 Firm
 Over 4.00
 Hard


#### **Quantity Modifiers**

Term	% of Dry Weight
trace	0 to 10
little	11 to 20
some	21 to 35
and/with	36 to 50

#### **Particle Size Identifications**


Boulder		Over 8 inch diameter
Cobbles		3 inch to 8 inch
Gravel	Coarse	1 inch to 3 inch
	Medium	1/2 inch to 1 inch
	Fine	4.75 mm to 1/2 inch
Sand	Coarse	2 mm to 4.75 mm
	Medium	0.425 mm to 2 mm
	Fine	0.075 mm to 0.425 mm
Silt/Clay		Below 0.075 mm





**BORING PLAN** 

Montgomery County Task Order #13 Subtask B Phase III Montgomery County, Maryland JOB NO.: 10-368.01 SCALE: N.T.S. DATE: 12/11/12



Proje	ect No. 10-368.01	LOG C	F BOR	REHC	DLE B-	51					Sheet 1 of 1			
CLIEN		mick Taylor, Inc		PROJ <b>N</b>	ECT: <b>IO Count</b>	y Tas	sk Or	der#	13 5	Subta	ısk B	(Pha	ıse 3)	
ARCH	HITECT/ENGINEER:			SITE:		Fra	nklin	Knol	ls. N	larvla	and			
					SA	MPLE		11.10.	10, 11	.u. y .u	TES	STS		
SURFA	ACE ELEV.: <b>283.5</b> ft.		GRAPHIC LOG	DЕРТН (FT)	BLOWS/6" N - VALUE RQD	NUMBER	ТҮРЕ	IN. RECOVERED IN. DRIVEN	MOISTURE (%)	DRY DENSITY (PCF)	Qu (TSF)	% PASSING #200 SIEVE	REMARKS/ ADDITIONAL DATA	
	3" Topsoil		283.2											
	Medium dense to dens brown SILTY FINE SAI trace of rock fragement	ND (SM) with mica and			3-6-9 N=15	1	SS	10/18 56%	12					
				5—	4-8-9 N=17	2	SS	8/18 44%	12					
	-become loose betwee	n 6 and 7.5 ft			4-3-6 N=9	3	SS	12/18 67%	14			22		
10.0			273.5	10	10-15-21 N=36	4	SS	7/18 39%	8					
WL WL	End of Boring @ 10 ft													
₩A	WATER LEVEL OBSERVATIONS AB C					Consultants, Inc. STARTED: 12				1/12	FINIS	SHED:	12/4/12	
WL Dry @ Drilling 9450 /					olis Road		DRIL	L CO.:	P	ABC DRILL RIG: B-61				
WL	Dry, caved in 6 ft @ 0			20706 306-3091		DRIL	LER:	PS ASS'T DRILLER			ER:			
WL	Dry, caved in 6 ft After	r 24 Hrs		e: 301-306-3091 301-306-3092				GED BY:	APPROVED:					

Proj	ect No. 10-368.01	LOG C	LOG OF BOREHOLE B-52							Sheet 1 of 1			
CLIEN		mick Taylor, Inc		PROJ N	IECT: <b>IIO Count</b> y	y Tas	sk Or	der#	13 8	Subta	ısk B	(Pha	ıse 3)
ARCH	HITECT/ENGINEER:	,		SITE:				Knol				•	
					SAI	MPLE		111101	113, 14	iai y ic	TES	STS	
SURFA	ACE ELEV.: <b>258.5</b> ft.		GRAPHIC LOG	<b>DEPTH (FT)</b>	BLOWS/6" N - VALUE RQD	NUMBER	ТҮРЕ	IN. RECOVERED IN. DRIVEN	MOISTURE (%)	DRY DENSITY (PCF)		SSING	REMARKS/ ADDITIONAL DATA
0.2	2" Topsoil		258.3										
	Brown and gray SILTY mica and rock fragmen	FINE SAND (SM) with ts				1	AU	18	13				CFA sampl
				- - 5-		2	AU	18	16			35	
21 7						3	AU	18	11				
10.0			248.5			4	AU	18	12				
5 (6)	End of Boring @ 10 ft												
A L		, borehole was drilled by method											
NA/A:	TED LEVEL ODGEDVATIO	MIC											
WATER LEVEL OBSERVATIONS  AB 0					Itants, In	C.		RTED:	12/4		FINIS	SHED:	12/4/12
WL Dry @ Drilling 9450 Lanha				m, MŒ	olis Road 20706					ABC	ABC DRILL RIG: B-61		
WL Dry, caved in 4.5 ft @ 0 Hrs Pho Fax:					306-3091 6-3092		DRIL	LER: GED BY:		PS	ASS'T DRILLER:		
ML WL	Dry, caved in 5 ft After	1 24 MIS	Fax: 301-306-3092							APPROVED:			

Proj	ject No. 10-368.01	LOG O	F BOR	REHC	DLE B-	53				Sheet 1 of 1					
CLIE		mick Taylor, Inc		PROJ N	ECT: <b>IO Count</b>	y Tas	sk Oı	der#	13 8	Subta	ısk B	(Pha	ıse 3)		
ARCI	HITECT/ENGINEER:			SITE:		Fra	nklin	Knol	ls N	larvla	and				
					SA	MPLE:		11101	,	iai y ic	TES	 STS			
QI IDE	ACE ELEV.: <b>240.5</b> ft.		GRAPHIC LOG	DЕРТН (FT)	BLOWS/6" N - VALUE RQD	NUMBER	TYPE	IN. RECOVERED IN. DRIVEN	MOISTURE (%)	DRY DENSITY (PCF)	Qu (TSF)	% PASSING #200 SIEVE	REMARKS/ ADDITIONAL DATA		
	2" Topsoil		240.3 317 131		шии		<del>                                     </del>					**	ш ( П		
	Loose brown and gray with mica and trace of r	SILTY FINE SAND (SM) ock fragements		-	3-4-5 N=9	1	SS	14/18 78%	14						
				- - 5-	2-3-3 N=6	2	SS	15/18 83%	22						
				-	3-4-5 N=9	3	SS	14/18 78%	18			28			
10.0		_ 2	230.5	- - - 10-	2-4-4 N=8	4	SS	7/18 39%	19						
WA WL WL	End of Boring @ 10 ft														
	TED LEVEL OBOSEN (ATIO	AIC .													
,,,,	ATER LEVEL OBSERVATIO			Itants, In	C.	STA	RTED:	12/4		FINIS	SHED:	12/4/12			
WL Dry @ Drilling 9450 A					olis Road 20706		DRILL CO.: AB			ABC	DRIL	L RIG:	B-61		
WL		y, caved in 6.5 ft @ 0 Hrs Pho					Phone: 301-306-3091				PS ASS'T DRILLER:				
WL	Dry, caved in 6.5 ft After	<sup>-</sup> 24 Hrs	Fax: 301-306-3092								APPROVED:				

Proje	ect No.	10-368.01		LOG (	OF BOF	REHO	OLE B-	54						5	Sheet 1 of 1							
CLIEN	NT:	McC	ormick Ta	ylor, Inc		PRO.		y Tas	sk Or	Order # 13 Subtask B (Ph				(Pha	ıse 3)							
ARCH	HITECT/EN	NGINEER:		•		SITE:		Fra	nklin	Knol	le M	larvla	and		<u> </u>							
							SA	MPLE:		11101	.0,	iai y ic	<del>-</del>					TESTS				
					GRAPHIC LOG	DЕРТН (FT)	BLOWS/6" N - VALUE RQD	NUMBER	TYPE	IN. RECOVERED IN. DRIVEN	MOISTURE (%)	DRY DENSITY (PCF)		SSING	REMARKS/ ADDITIONAL DATA							
		/.: <b>237.0</b> ft.					B.N.	ž		ZZ	M	P.F.	σË	%#	<u> </u>							
`	3" Topso Loose re SAND (\$	oil eddish browr SM) with mic	and gray a	SILTY FINE	236.7		2-3-4 N=7	1	SS	9/18 50%	18											
	-become	e medium de	nse betwe	en 3.5 and 5 ft		5—	3-5-6 N=11	2	SS	14/18 78%	16			28								
							2-2-3 N=5	3	SS	16/18 89%	21											
10.0				-	227.0	- - 10-	2-3-4 N=7	4	SS	12/18 67%	17											
	End of E	Boring @ 10	ft																			
WA	TER LEVE	EL OBSERVA	TIONS		_ AB C	onsu	Itants, In	C.	STAI	RTED:	12/3	3/12	FINIS	SHED:	12/3/12							
WL		Dry @	) Drilling		Annap	olis Road		DRIL	RILL CO.: ABC			DRILL RIG: B-61		B-61								
WL	Dry, ca	ved in 6 ft @	) 0 Hrs		ham, MD 20706 ne: 301-306-3091						PS ASS'T DRILLER:											
WL	Dry, ca	ved in 6 ft A	for 24 Hrs Fax: 301-306-3092					LOGGED BY: APPROVED:														

Proj	ject No. 10-368.01	LOG O	F BOF	REHC	DLE B-	55					Sheet 1 of 1				
CLIE		rmick Taylor, Inc		PROJ <b>N</b>	ECT: <b>//O Count</b>	y Tas	sk Oı	der#	13 5	Subta	ısk B	(Pha	ıse 3)		
ARCI	HITECT/ENGINEER:			SITE:		Fra	nklin	Knol	ls. N	larvia	and				
					SA	MPLE			,	<b>y</b>	TES	 3TS			
SURF	ACE ELEV.: <b>259.5</b> ft.		GRAPHIC LOG	ОЕРТН (FT)	BLOWS/6" N - VALUE RQD	NUMBER	TYPE	IN. RECOVERED IN. DRIVEN	MOISTURE (%)	DRY DENSITY (PCF)	Qu (TSF)	% PASSING #200 SIEVE	REMARKS/ ADDITIONAL DATA		
0.4	5" Topsoil  Loose to very dense b FINE SAND (SM) with	rown and gray SILTY mica and rock fragments	259.1		2-3-3 N=6	1	SS	9/18 50%	11						
				5—	2-4-9 N=13	2	SS	10/18 56%	20						
					3-51/6"	3	SS	9/12 75%	9			22			
10.0			249.5	10—	35-51/6"	4	SS	7/12 58%	5						
WA WL WL	Auger refusal @ 9.5 ft														
WA	TER LEVEL OBSERVATION	ΔRC	Oneu	Itants, In	ıC	STA	RTED:	12/4	1/12	FINIS	SHED:	12/4/12			
WL	Dry @ I	Drilling 1	Annap	olis Road	ο.		L CO.:		ABC			B-61			
WL	Dry, caved in 6.5 ft @ 0	Lanham MD 20706						LER:							
WL	Dry, caved in 6.5 ft After				6-3092			GED BY:		. •	PS ASS'T DRILLER:  APPROVED:				
$ \smile $	<u> </u>						LUG	JLU D1.			1 456	WED.			

Proj	ect No. 10-368.01	LOG O	F BOR	REHC	DLE B-	56					Sheet 1 of 1			
CLIEN		mick Taylor, Inc		PROJ N	ECT: <b>IO Count</b>	y Tas	sk Oı	der#	13 8	Subta	ask B	(Pha	ıse 3)	
ARCH	HITECT/ENGINEER:			SITE:		Fra	nklin	Knol	le M	larvis	and			
					SA	MPLE		111101	10, 11	iai y ic	TES	STS		
QI IDE.	ACE ELEV.: <b>266.0</b> ft.		GRAPHIC LOG	DЕРТН (FT)	BLOWS/6" N - VALUE RQD	NUMBER	TYPE	IN. RECOVERED IN. DRIVEN	MOISTURE (%)	DRY DENSITY (PCF)	Qu (TSF)	% PASSING #200 SIEVE	REMARKS/ ADDITIONAL DATA	
	3" Topsoil		265.7		ш 2 ш							0/#		
	Loose to medium dens SAND (SM) with mica a	e brown and gray SILTY and rock fragments			1-1-4 N=5	1	SS	7/18 39%	17					
					5-7-14 N=21	2	SS	10/18 56%	16			24		
	-become dense betwee	en 6 and 7.5 ft		-	7-21-19 N=40	3	SS	8/18 44%	6					
10.0		2	256.0	_ _ _ 10—	3-8-16 N=24	4	SS	13/18 72%	17					
WA WL WL	End of Boring @ 10 ft													
WA	TER LEVEL OBSERVATIO	AB C	Consultants, Inc. STARTED: 12				12/3	3/12	FINIS	SHED:	12/3/12			
WL Dry @ Drilling 9450 /					50 Annapolis Road			L CO.:	-	ABC	DRILL RIG: B-61			
WL Dry, caved in 6.5 ft @ 0 Hrs Phone					Inham, MD 20706 none: 301-306-3091				PS ASS'T DRILLER:					
WL	Dry, caved in 6.5 ft After	r 24 Hrs		ie: 301-306-3091 301-306-3092				LOGGED BY:				APPROVED:		

Proje	ect No. 10-368.01	LOG O	F BOR	REHC	DLE B-	57						;	Sheet 1 of 1
CLIEN		mick Taylor, Inc		PROJ N	ECT: <b>IO Count</b>	y Tas	sk Oı	der#	13 5	Subta	ısk B	(Pha	ıse 3)
ARCH	IITECT/ENGINEER:			SITE:		Fra	nklin	Knol	ls N	larvia	and		
					SA	MPLE		111101	10, 11	iai y ic	TES	STS	
SLIDEA	NCE ELEV.: <b>268.5</b> ft.		GRAPHIC LOG	DЕРТН (FT)	BLOWS/6" N - VALUE RQD	NUMBER	TYPE	IN. RECOVERED IN. DRIVEN	MOISTURE (%)	DRY DENSITY (PCF)	Qu (TSF)	% PASSING #200 SIEVE	REMARKS/ ADDITIONAL DATA
0.3	3" Topsoil		268.2		ш 2 ш	_						0/#	
	Medium dense brown a SAND (SM) with mica				2-5-8 N=13	1	SS	9/18 50%	6				
	-become very dense be	etween 3.5 and 5 ft		5—	22-35-51 N=86	2	SS	9/18 50%	6			28	
				  	7-12-19 N=31	3	SS	16/18 89%	13				
10.0		_ 2	258.5	10—	6-12-16 N=28	4	SS	14/18 78%	17				
WAT WL WL	End of Boring @ 10 ft												
WA7	TER LEVEL OBSERVATIO	NS			ltants, In	C.	STA	RTED:	12/3	3/12	FINIS	SHED:	12/3/12
WL	Dry @ D	Orilling 1	9450 <i>F</i>	Annap m Mr	olis Road 20706		DRIL	L CO.:	A	ABC	DRIL	L RIG:	B-61
WL	Dry, caved in 6 ft @ 0	Hrs	Phone	: 301-	306-3091		DRIL	LER:		PS	ASS"	T DRILLI	≣R:
WL	Dry, caved in 6 ft After	r 24 Hrs	Fax: 3	01-30	6-3092		LOG	GED BY:			APPE	ROVED:	

Proje	ect No. 10-368.01	LOC	G OF BOR	REHC	DLE B-	58						;	Sheet 1 of 1
CLIEN		mick Taylor, Inc		PROJ N	ECT: <b>IO Count</b>	y Tas	sk Oı	der#	13 9	Subta	ısk B	(Pha	ise 3)
ARCH	ITECT/ENGINEER:	<u> </u>		SITE:		Fra	nklin	Knol	le M	larvis	and		
					SA	MPLE		111101	, 10	iai y it	TES	STS	
SLIDEA	NCE ELEV.: <b>271.0</b> ft.		GRAPHIC LOG	DЕРТН (FT)	BLOWS/6" N - VALUE RQD	NUMBER	TYPE	IN. RECOVERED IN. DRIVEN	MOISTURE (%)	DRY DENSITY (PCF)		SSING	REMARKS/ ADDITIONAL DATA
	3" Topsoil		270.7 \( \frac{\si^1 \lambda}{2} \) \( \frac{\si^1 \lambda}{2} \)		шии			==				*	шап
	Dense to very dense br FINE SAND (SM) with	own and gray SILTY mica			3-18-37 N=55	1	SS	10/18 56%	8				
				5—	30-51/5"	2	SS	7/11 64%	7			19	
					51/6"	3	SS	3/6 50%	8				
10.0			261.0	— — — —	30-51/4"	4	SS	7/10 70%	7				
WAT WL WL	Auger refusal @ 9.5 ft			, <del>-</del>									
WAT	TER LEVEL OBSERVATIO	19-			Itants, In	C.	STA	RTED:	12/3		FINIS	SHED:	12/3/12
WL		rilling	<b>Lanha</b>	m, ME	olis Road 20706		DRIL	L CO.:	- 1	ABC	DRIL	L RIG:	B-61
WL	Dry, caved in 6 ft @ 0				306-3091 6-3092		DRIL	LER:		PS	ASS"	T DRILLI	ER:
WL	Dry, caved in 5.5 ft After	· 24 Hrs	гах. З	0 1-30	0-3032		LOG	GED BY:			APP	ROVED:	

Proje	ect No. 10-368.01	LOG (	OF BOR	REHC	DLE B-	59							Sheet 1 of 1
CLIEN		mick Taylor, Inc		PROJ <b>N</b>	ECT: <b>IO Count</b>	y Tas	sk Oı	der#	13 5	Subta	sk B	(Pha	ase 3)
ARCH	IITECT/ENGINEER:			SITE:		Fra	nklin	Knol	ls. N	larvla	and		
					SA	MPLE			,	.u. y .	TES	 3TS	
SURFA	ACE ELEV.: <b>273.0</b> ft.		GRAPHIC LOG	DЕРТН (FT)	BLOWS/6" N - VALUE RQD	NUMBER	TYPE	IN. RECOVERED IN. DRIVEN	MOISTURE (%)	DRY DENSITY (PCF)	Qu (TSF)	% PASSING #200 SIEVE	REMARKS/ ADDITIONAL DATA
0.3	3" Topsoil	OII TV FINE OAND	272.7										
	Very dense brown and (SM) with mica	gray SILTY FINE SAND		_	12-27-33 N=60	1	SS	11/18 61%	10				
					7-51/6"	2	SS	7/12 58%	11				
					17-37-38 N=75	3	SS	14/18 78%	9			24	
10.0			263.0	_ _ _ 10	17-34-45 N=79	4	SS	15/18 83%	8				
WL WL	End of Boring @ 10 ft												
WA <sup>-</sup>	TER LEVEL OBSERVATIO	NS	AB C	onsu	Itants, In	C.	STA	RTED:	12/4	1/12	FINIS	SHED:	12/4/12
WL	Dry @ D	rilling	9450 A	\nnap	olis Road		DRIL	L CO.:	P	ABC	DRIL	L RIG:	B-61
WL	Dry, caved in 6 ft @ 0	Hrs			20706 306-3091		DRIL	LER:		PS	ASS"	T DRILLE	ER:
WL	Dry, caved in 6 ft After	· 24 Hrs			6-3092		LOG	GED BY:			APP	ROVED:	

Proj	ect No. 10-368.01	LOG C	F BOR	REHC	DLE B-6	60						;	Sheet 1 of 1
CLIEI		nick Taylor, Inc		PROJ N	ECT: <b>IO Count</b>	y Tas	sk Or	der#	13 5	Subta	ısk B	(Pha	ıse 3)
ARCI	HITECT/ENGINEER:			SITE:		Fra	nklin	Knol	ls M	larvia	and		
					SA	MPLE		11101	,	.u. y .	TES	STS	
SURF	ACE ELEV.: <b>263.5</b> ft.		GRAPHIC LOG	DЕРТН (FT)	BLOWS/6" N - VALUE RQD	NUMBER	TYPE	IN. RECOVERED IN. DRIVEN	MOISTURE (%)	DRY DENSITY (PCF)	Qu (TSF)	% PASSING #200 SIEVE	REMARKS/ ADDITIONAL DATA
	4" Topsoil		263.2										
	Loose to dense brown a SAND (SM) with mica	and gray SILTY FINE		-	3-4-4 N=8	1	SS	10/18 56%	12				
				- - 5-	3-2-4 N=6	2	SS	15/18 83%	17				
2				-	14-26-23 N=49	3	SS	12/18 67%	10			15	
10.0			253.5		7-17-31 N=48	4	SS	13/18 72%	11				
MA LANGE COCK ARUS MONT. CO. LASN ONDER #13 SUBLIASN B (FRASE 5) GF) 3 B. CONS. GD   7/17/13	End of Boring @ 10 ft												
∯ WA	TER LEVEL OBSERVATIO	NS	AB C	onsu	Itants, In	C.	STAI	RTED:	12/3	3/12	FINIS	SHED:	12/3/12
WL WL	Dry @ D	rilling	9450 A	Annap	olis Road		DRIL	L CO.:	P	ABC	DRIL	L RIG:	B-61
WL	Dry, caved in 6.5 ft @ 0	Hrs			20706 306-3091		DRIL	LER:		PS	ASS"	T DRILLI	ER:
WL	Dry, caved in 6 ft After	24 Hrs			6-3092		LOG	GED BY:			APP	ROVED:	

Pro	ject No.	10-368.01	LOG	OF BOF	REHO	DLE B-	61						;	Sheet 1 of 1
CLIE	NT:	McCori	mick Taylor, Inc		PROJ N	ECT: <b>//O Count</b>	y Ta	sk Oı	der#	13 8	Subta	ısk B	(Pha	ase 3)
ARC	HITECT/EI	NGINEER:			SITE:		Fra	nklin	Knol	ls. N	larvla	and		
						SA	MPLE			_,		TES	STS	
SURF	FACE ELE\	/.: <b>270.0</b> ft.		GRAPHIC LOG	ОЕРТН (FT)	BLOWS/6" N - VALUE RQD	NUMBER	TYPE	IN. RECOVERED IN. DRIVEN	MOISTURE (%)	DRY DENSITY (PCF)	Qu (TSF)	% PASSING #200 SIEVE	REMARKS/ ADDITIONAL DATA
	3" Tops	oil		269.7										
	Medium SILTY F fragmen	FINE SAND (SM	dense brown and gray 1) with mica and rock			3-5-17 N=22	1	SS	9/18 50%	12				
					_ _ _ 5—	16-26-35 N=61	2	SS	15/18 83%	7				
2						20-21-14 N=35	3	SS	7/18 39%	9			20	
10.0				260.0		51/6"	4	SS	5/6 83%	3				
10.0 WL	Auger re	efusal @ 9 ft												
W.	ATER LEVI	EL OBSERVATIO	NS	AB C	onsu	Itants, In	IC.	STA	RTED:	11/30	)/12	FINIS	SHED:	11/30/12
WL		Dry @ D	rilling	9450	Annap	olis Road		DRIL	L CO.:	A	ABC	DRIL	L RIG:	B-61
WL	Dry, cav	ved in 6.5 ft @ 0	Hrs			20706 306-3091		DRIL	LER:		PS	ASS"	T DRILLI	ER:
WL	Dry, ca	ved in 6.5 ft After	· 24 Hrs			6-3092		LOG	GED BY:				ROVED:	

Proj	ect No. 10-368.01	LOG (	OF BOR	REHC	DLE B-	62						;	Sheet 1 of 1
CLIEN		mick Taylor, Inc		PROJ N	ECT: <b>IO Count</b>	y Tas	sk Oı	der#	13 8	Subta	ısk B	(Pha	ase 3)
ARCH	HITECT/ENGINEER:	-		SITE:		Fra	nklin	Knol	ls N	larvia	and		
					SA	MPLE		11101	,	iai y ic	TES	 STS	
SURF	ACE ELEV.: <b>296.5</b> ft.		GRAPHIC LOG	<b>DEPTH (FT)</b>	BLOWS/6" N - VALUE RQD	NUMBER	TYPE	IN. RECOVERED IN. DRIVEN	MOISTURE (%)	DRY DENSITY (PCF)		SSING	REMARKS/ ADDITIONAL DATA
	4" Topsoil		296.2										
	Medium dense to dens FINE SAND (SM) with	e brown and gray SILTY mica			6-10-15 N=25	1	SS	8/18 44%	17				
				- - 5-	7-13-18 N=31	2	SS	15/18 83%	11				
				-	10-15-20 N=35	3	SS	12/18 67%	12			23	
10.0			286.5		7-17-29 N=46	4	SS	13/18 72%	9				
WA WL WL	End of Boring @ 10 ft												
\\/^	TER LEVEL OBSERVATIO	NS							44/0	2/40			44/00::-
WL		rilling			ltants, In olis Road	C.		RTED:	11/30			SHED:	11/30/12
WL	Dry, caved in 6.5 ft @ 0		Lanha	m, ME	20706			L CO.:		ABC		L RIG:	B-61
VVL					306-3091 6-3092		DRIL	LER:		PS	ASS"	T DRILLI	ER:
WL	Dry, caved in 6 ft After	<sup>-</sup> 24 Hrs	1 ax. 3	0 1-30	J-JUJZ		LOG	GED BY:			APP	ROVED:	

Proj	ect No. 10-368.01	LOG C	OF BOR	REHO	OLE B-6	63						;	Sheet 1 of 1
CLIEN		mick Taylor, Inc		PROJ	ECT: <b>IO Count</b>	y Tas	sk Oı	der#	13 8	Subta	ısk B	(Pha	ıse 3)
ARCH	HITECT/ENGINEER:			SITE:		Fra	nklin	Knol	ls. N	larvla	and		
					SA	MPLE			,	.u. y .	TES	STS	
SURF	ACE ELEV.: <b>303.0</b> ft.		GRAPHIC LOG	ОЕРТН (FT)	BLOWS/6" N - VALUE RQD	NUMBER	TYPE	IN. RECOVERED IN. DRIVEN	MOISTURE (%)	DRY DENSITY (PCF)	Qu (TSF)	% PASSING #200 SIEVE	REMARKS/ ADDITIONAL DATA
0.4	5" Topsoil  Medium dense reddish FINE SAND (SM) with	brown to brown SILTY	302.6	_	3-4-11 N=15	1	SS	7/18 39%	16				
	-become dense betwee	en 3.5 and 5 ft		5—	10-18-26 N=44	2	SS	18/18 100%	15			29	
					7-11-15 N=26	3	SS	12/18 67%	13				
10.0			293.0	10—	5-9-12 N=21	4	SS	16/18 89%	14				
WA WL WL	End of Boring @ 10 ft												
WA	TER LEVEL OBSERVATION	DNS			ltants, In	C.	STA	RTED:	11/30	)/12	FINIS	SHED:	11/30/12
WL	Dry @ E	Orilling Prilling	9450 /	Annap	olis Road 20706		DRIL	L CO.:	A	ABC	DRIL	L RIG:	B-61
WL	Dry, caved in 6.5 ft @ 0	Hrs	Phone	e: 301-	306-3091		DRIL	LER:		PS	ASS'	T DRILLI	ER:
WL	Dry, caved in 6 ft Afte	r 24 Hrs	Fax: 3	01-30	6-3092		LOG	GED BY:			APP	ROVED:	

Proje	ect No. 10-368.01	LOG C	F BOF	REHC	DLE B-	64						;	Sheet 1 of 1
CLIEN		mick Taylor, Inc		PROJ <b>N</b>	ECT: <b>IO Count</b>	y Tas	sk Oı	der#	13 8	Subta	ısk B	(Pha	ase 3)
ARCH	IITECT/ENGINEER:			SITE:		Fra	nklin	Knol	ls. N	larvia	and		
					SA	MPLE			,	<b>y</b>	TES	STS	
SURFA	ACE ELEV.: <b>277.5</b> ft.		GRAPHIC LOG	ОЕРТН (FT)	BLOWS/6" N - VALUE RQD	NUMBER	TYPE	IN. RECOVERED IN. DRIVEN	MOISTURE (%)	DRY DENSITY (PCF)	Qu (TSF)	% PASSING #200 SIEVE	REMARKS/ ADDITIONAL DATA
0.3	3" Topsoil		277.2										
	Medium dense to very SILTY FINE SAND (SN fragments	dense brown and gray			3-10-11 N=21	1	SS	12/18 67%	10				
				_ _ _ 5—	5-8-13 N=21	2	SS	11/18 61%	10			26	
					18-51/4"	3	SS	8/10 80%	7				
10.0			267.5	10—	☑ 51/3"	4	SS	2/3 67%	4				
WAT WL WL	Auger refusal @ 9 ft												
WA	TER LEVEL OBSERVATIC	NS	_ AB C	onsu	Itants, In	ıc.	STA	RTED:	11/30	0/12	FINIS	SHED:	11/30/12
WL	Dry @ D	rilling	9450	Annap	olis Road		DRIL	L CO.:	A	ABC	DRIL	L RIG:	B-61
WL	Dry, caved in 6 ft @ 0	Hrs			20706 306-3091		DRIL	LER:		PS	ASS"	T DRILLI	ER:
WL	Dry, caved in 6 ft Afte	<sup>-</sup> 24 Hrs			6-3092		LOG	GED BY:			APP	ROVED:	

Proje	ect No. 10-368.01	LOG	OF BOR	EHC	OLE B-	<b>35</b>						;	Sheet 1 of 1
CLIEN		mick Taylor, Inc		PROJ	IECT: <b>IIO Count</b> y	y Tas	sk Or	der#	13 8	Subta	ısk B	(Pha	ise 3)
ARCH	HITECT/ENGINEER:	,		SITE:				Kno				•	
					SA	MPLE:		11110	113, 11	iai y ic	TES	STS	
SURF/	ACE ELEV.: <b>285.5</b> ft.		GRAPHIC LOG	<b>DEPTH (FT)</b>	BLOWS/6" N - VALUE RQD	NUMBER	TYPE	IN. RECOVERED IN. DRIVEN	MOISTURE (%)	DRY DENSITY (PCF)		SSING	REMARKS/ ADDITIONAL DATA
0.3	4" Topsoil		285.2				<u> </u>					- "	
	Brown and gray SILTY mica	FINE SAND (SM) with				1	AU	18	5				CFA samp
						2	AU	18	7			21	
21 72				- - -		3	AU	18	6				
10.0			275.5	10—		4	AU	18	10				
5	End of Boring @ 10 ft												
A L		, borehole was drilled by method											
ON NAVA	TED I EVEL OBSERVATIO	INIC I											
WL WL	TER LEVEL OBSERVATIO	43.			Itants, In olis Road	C.		RTED:	11/30			SHED:	11/30/12
WL	Dry @ D  Dry, caved in 6 ft @ 0	urilling Hrs	Lanha	m, MŒ	20706			L CO.:	, A	ABC		L RIG:	B-61
WL	Dry, caved in 6 ft After				306-3091 6-3092			LER:		PS		T DRILLI	ER:
	Dry, Caved in Oil Allei	271113			<b>-</b>		LOG	GED BY:			APP	ROVED:	

Pro	ject No. 10-3	368.01	LOG C	F BOF	REHC	DLE B-	66						;	Sheet 1 of 1
CLIE	NT:	McCormick T	aylor, Inc		PROJ <b>N</b>	ECT: <b>IO Count</b>	y Tas	sk Oı	der#	13 8	Subta	ısk B	(Pha	ase 3)
ARC	HITECT/ENGINE	ER:			SITE:		Fra	nklin	Knol	ls. N	larvia	and		
						SA	MPLE			,		TES	STS	
SURF	ACE ELEV.: <b>29</b> 9	<b>).5</b> ft.		GRAPHIC LOG	ОЕРТН (FT)	BLOWS/6" N - VALUE RQD	NUMBER	TYPE	IN. RECOVERED IN. DRIVEN	MOISTURE (%)	DRY DENSITY (PCF)	Qu (TSF)	% PASSING #200 SIEVE	REMARKS/ ADDITIONAL DATA
0.3	4" Topsoil			299.2										
	Medium dens SILTY FINE S fragments	e to very dense I SAND (SM) with	orown and gray mica and rock			3-7-9 N=16	1	SS	13/18 72%	15				
						12-14-23 N=37	2	SS	12/18 67%	13				
						20-51/3"	3	SS	7/9 78%	8			19	
10.0			_	289.5	10—	51/6"	4	SS	6/6 100%	9				
WA WL WL	Auger refusal	@ 9 ft												
WA	ATER LEVEL OB	SERVATIONS		_ AB C	onsu	Itants, In	C.	STA	RTED:	11/30	0/12	FINIS	SHED:	11/30/12
WL	Dry	@ Drilling		9450	Annap	olis Road		DRIL	L CO.:	P	ABC	DRIL	L RIG:	B-61
WL	Dry, caved in 6	6.5 ft @ 0 Hrs				20706 306-3091		DRIL	LER:		PS	ASS"	T DRILLI	ER:
WL	Dry, caved in 6	6.5 ft After 24 Hrs				6-3092		LOG	GED BY:			APP	ROVED:	

Proje	ect No. 10-368.01	LOG (	OF BO	REH	OLE B-	67						:	Sheet 1 of 1
CLIEN		nick Taylor, Inc		PRO.	IECT: <b>VIO Count</b>	y Tas	sk Oı	der#	13 \$	Subta	isk B	(Pha	ase 3)
ARCH	ITECT/ENGINEER:			SITE:		Fra	nklin	Knol	ls. N	larvia	and		
					SA	MPLE		11.101	, ,,	.u. y .	TES	STS	
SURFA	.CE ELEV.: <b>307.0</b> ft.		GRAPHIC LOG	ОЕРТН (FT)	BLOWS/6" N - VALUE RQD	NUMBER	TYPE	IN. RECOVERED IN. DRIVEN	MOISTURE (%)	DRY DENSITY (PCF)	Qu (TSF)	% PASSING #200 SIEVE	REMARKS/ ADDITIONAL DATA
	5" Topsoil Loose brown SILTY FIN	E SAND (SM) with mica	306.6		2-4-5 N=9	1	SS	12/18 67%	18				
				5-	4-4-4 N=8	2	SS	17/18 94%	15			29	
	Soft to firm reddish brow CLAY (CL) with sand	n to brown SILTY	301.0		1-2-2 N=4	3	SS	18/18 100%	24			84	LL = 30 PL = 19 PI = 11
10.0		-	297.0	- - 10-	2-4-6 N=10	4	SS	17/18 94%	17				
	End of Boring @ 10 ft												
WAT	TER LEVEL OBSERVATION	18	AB (	Consu	Itants, In	IC.	STA	RTED:	11/20	)/12	FINIS	SHED:	11/20/12
WL	Dry @ Dr	illing	9450	Annap	olis Road		DRIL	.L CO.:		ABC	DRIL	L RIG:	B-61
WL	Dry, caved in 6 ft @ 0 l	Hrs			20706 306-3091		DRIL	LER:		PS	ASS'	T DRILL	ER:
WL	Dry, caved in 6.5 ft After	24 Hrs			6-3092		LOG	GED BY:			APPI	ROVED:	


Proj	ect No. 10-368.01	LOG	OF BOR	EHC	DLE B-	86						;	Sheet 1 of 1
CLIEN		mick Taylor, Inc		PROJ <b>N</b>	ECT: <b>IO Count</b>	y Tas	sk Or	der#	13 5	Subta	ısk B	(Pha	ase 3)
ARCI	HITECT/ENGINEER:	<u> </u>		SITE:		Fra	nklin	Knol	le M	larvia	and		
					SA	MPLE		11101	13, 14	iai y ic	TES	STS	
CLIDE	AOG 51 51/1 207 5 #		GRAPHIC LOG	DЕРТН (FT)	BLOWS/6" N - VALUE RQD	NUMBER	TYPE	IN. RECOVERED IN. DRIVEN	MOISTURE (%)	DRY DENSITY (PCF)	Qu (TSF)	% PASSING #200 SIEVE	REMARKS/ ADDITIONAL DATA
	ACE ELEV.: 307.5 ft. 4" Topsoil		307.2 24 1/2 3.54		<u> </u>		-	==			00	8 #	БФП
		e brown and gray SILTY mica			1-2-2 N=4	1	SS	8/18 44%	16				
				5—	2-2-3 N=5	2	SS	14/18 78%	17				
				_ _ _	4-6-6 N=12	3	SS	17/18 94%	10			18	
10.0		_	297.5	10	4-6-7 N=13	4	SS	13/18 72%	15				
WA WL WL	End of Boring @ 10 ft												
WA	TER LEVEL OBSERVATIO	43-			Itants, In	C.	STAI	RTED:	11/20	)/12	FINIS	SHED:	11/20/12
WL		rilling	9450 <i>A</i> Lanha	Annap m, M□	olis Road 20706		DRIL	L CO.:	A	ABC	DRIL	L RIG:	B-61
WL	Dry, caved in 6.5 ft @ 0		Phone	: 301-	306-3091		DRIL	LER:		PS	ASS"	T DRILLI	ER:
WL	Dry, caved in 6 ft After	<sup>-</sup> 24 Hrs	Fax: 3	U1-306	6-3092		LOG	GED BY:			APPE	ROVED:	

1.2.2   1   SS   11/18   12     12     12/18   13     15/18   13     15/18   14     15/18	Project No. 10-368.01 LOG OF BOREHOLE B-69										Sheet 1 of 1						
SURFACE ELEV.: 297.5 ft.													Subtask B (Phase 3)				
SURFACE ELEV: 297.5 ft.  0.3. 4" Topsoil  Loose to medium dense brown and gray SILTY  FINE SAND (SM) with mice  SURFACE ELEV: 297.5 ft.  0.3. 4" Topsoil  1-2-2 1 SS 10/16 12 23  1-2-2 1 SS 10/16 12	ARCHITEC		SITE:														
1													<u> </u>				
1	SURFACE E	ELEV: <b>297.5</b> ft.			GRAPHIC LOG	DЕРТН (FT)	BLOWS/6" N - VALUE RQD	NUMBER	TYPE	IN. RECOVERED IN. DRIVEN	MOISTURE (%)	DRY DENSITY (PCF)	Qu (TSF)	% PASSING #200 SIEVE	REMARKS/ ADDITIONAL DATA		
FINE SAND (SM) with mica  1.2.2 1 SS 11/18 12  6.8.11 2 SS 10/18 12  6.8.11 2 SS 10/18 12  7.10-13 4 SS 15/18 13  83%  10.0 287.5 10  MATER LEVEL OBSERVATIONS  WATER LEVEL OBSERVATIONS  WL Dry @ Dmiling  WL Dry @ Dmiling  WL Dry @ Dmiling  WL Dry caved in 6 ft @ 0 Hrs  WL Dry caved in 6 ft @ 0 Hrs  WL Dry caved in 6 ft @ 0 Hrs  WL Dry caved in 6 ft @ 0 Hrs  WL Dry caved in 6 ft @ 0 Hrs  WL Dry caved in 6 ft @ 0 Hrs  WL Dry caved in 6 ft @ 0 Hrs  WL Dry caved in 6 ft @ 0 Hrs  WL Dry caved in 6 ft @ 0 Hrs  WL Dry caved in 6 ft @ 0 Hrs  WL Dry caved in 6 ft @ 0 Hrs  PS ASST DRILER: PS ASST DRILER:	0.3_4" T	opsoil			297.2												
WATER LEVEL OBSERVATIONS WL Dry @ Drilling WL Dry, caved in 6 ft @ 0 Hrs WL Dry, caved in 6 ft @ 0 Hrs WL Dry, caved in 6 ft @ 0 Hrs Fax: 301-306-3091 Fax: 301-306-3092	Loos FINI	se to medium o	dense brown with mica	and gray SILTY		-		1	SS		12						
N=15						_ _ _ 5—		2	SS	10/18 56%	12			23			
N=23						-		3	SS		13						
WATER LEVEL OBSERVATIONS  WL Dry @ Drilling  WL Dry, caved in 6 ft @ 0 Hrs  WL Dry caved in 6 ft @ 0 Hrs  WL Dry caved in 6 ft @ 1 After 24 Hrs	10.0				287.5			4	SS	12/18 67%	10						
WL Dry @ Drilling WL Dry, caved in 6 ft @ 0 Hrs  WI Dry, caved in 6 ft After 24 Hrs  WI Dry, caved in 6 ft After 24 Hrs	End	of Boring @ 1	O ft														
WL Dry @ Drilling  WL Dry, caved in 6 ft @ 0 Hrs  WI Dry, caved in 6 ft After 24 Hrs  WI Dry caved in 6 ft After 24 Hrs	WATER LEVEL OBSERVATIONS AR C						onsultante Inc			STARTED: 11/20/			FINISHED: 11/20/12				
WL Dry, caved in 6 ft @ 0 Hrs  Lanham, MD 20706 Phone: 301-306-3091 Fax: 301-306-3092	WL	Dry @ Drilling 9450 Ann					nnapolis Road										
MI Dry cayod in 6 ft After 24 Hz	WL Dr	Lanham, MD 20706							_								
ECOCOLD DI. AFFICONTO	WL Dr	y, caved in 6 ft	After 24 Hrs	Filorie. 301-300-3091					LOGGED BY:								

Pro	ject No. 10-368.01	LOG (	LOG OF BOREHOLE B-70							Sheet 1 of 1			
CLIE		mick Taylor, Inc		PROJ N		y Tas	sk Order # 13 Subtask B (Phase 3)				ase 3)		
ARC	HITECT/ENGINEER:			SITE: Franklin Knolls,						Maryland			
					SA	MPLE			,	TESTS			
SURF	ACE ELEV.: <b>290.5</b> ft.		GRAPHIC LOG	ОЕРТН (FT)	BLOWS/6" N - VALUE RQD	NUMBER	TYPE	IN. RECOVERED IN. DRIVEN	MOISTURE (%)	DRY DENSITY (PCF)	Qu (TSF)	% PASSING #200 SIEVE	REMARKS/ ADDITIONAL DATA
	3" Topsoil		290.2									- 1-	
	Loose brown and gray with mica	SILTY FINE SAND (SM)		— — —	2-2-4 N=6	1	SS	10/18 56%	14				
					3-4-4 N=8	2	SS	14/18 78%	18			36	
2					3-4-5 N=9	3	SS	9/18 50%	21				
10.0			280.5	— — — 10—	1-2-2 N=4	4	SS	16/18 89%	22				
10.00 WL WL WL	End of Boring @ 10 ft												
W.	ATER LEVEL OBSERVATIO	NS	AR C	onsu	Itants, In	C	STA	RTED:	11/20	)/12	FINIS	SHED:	11/20/12
WL	Dry @ D	rilling	9450	Annap	olis Road	٠.	DRIL	L CO.:		ABC	DRIL	L RIG:	B-61
WL	Dry, caved in 6.5 ft @ 0	Hrs 25			20706 306-3091			LER:		PS		T DRILLI	
WL	Dry, caved in 6 ft After	24 Hrs			6-3092			GED BY:				ROVED:	


Proj	ject No. 10-368.01	LOG	LOG OF BOREHOLE B-71							Sheet 1 of 1				
CLIEN		mick Taylor, Inc		PROJ N	ECT: <b>IO Count</b>	y Tas	sk Oı	der#	13 8	Subta	ısk B	(Pha	ise 3)	
ARCH	RCHITECT/ENGINEER: SITE:										Manuland			
					SA	MPLE:	ranklin Knolls, Maryland ES TESTS							
SURF	ACE ELEV.: <b>292.5</b> ft.		GRAPHIC LOG	ОЕРТН (FT)	BLOWS/6" N - VALUE RQD	NUMBER	TYPE	IN. RECOVERED IN. DRIVEN	MOISTURE (%)	DRY DENSITY (PCF)		SSING	REMARKS/ ADDITIONAL DATA	
	4" Topsoil	CEINIE CANID (OM)	292.2 2 2 2											
	Brown and gray SILTY mica and rock fragmer	FINE SAND (SM) with ots				1	AU	18	10				CFA sampl	
						2	AU	18	7			23		
2						3	AU	18	6					
10.0			282.5			4	AU	18	4					
PORING COG ABOS MON. CO. LASA ORDER #13 SUBLASA B (FRASE 5) GF. 3 B CONS. GD. 7/7/13  MA  TA  A  A  A  A  A  A  A  A  A  A  A	End of Boring @ 10 ft  Due to over head utility continuous flight auger	y, borehole was drilled by method												
10-308 MONI CO. 1A	NTER LEVEL OBSERVATION	DNS	AB C	onsu	Itants, In	C.	STA	RTED:	11/20	0/12	FINIS	SHED:	11/20/12	
WL	Dry @ [	Drilling 1	9450 A	Annap	olis Road 20706		DRIL	L CO.:	A	ABC	DRIL	L RIG:	B-61	
WL	Dry, caved in 6 ft @ 0	) Hrs	Phone	e: 301-	306-3091		DRIL	LER:		PS	ASS"	T DRILLI	ER:	
ML WL	Dry, caved in 6.5 ft After	er 24 Hrs	Phone: 301-306-3091 Fax: 301-306-3092					LOGGED BY:				APPROVED:		

Proj	ect No. 10-368.01	LOG (	LOG OF BOREHOLE B-72							Sheet 1 of 1				
CLIEI		mick Taylor, Inc		PROJ N		y Tas	sk Order # 13 Subtask B (Phase 3)				ase 3)			
ARCI	HITECT/ENGINEER:	-		SITE:		Fra	nklin	Knol	le M	, Maryland				
					SA	MPLE		111101	10, 11	TESTS				
CUDE	ACE ELEV. 200 0 #		GRAPHIC LOG	DЕРТН (FT)	BLOWS/6" N - VALUE RQD	NUMBER	TYPE	IN. RECOVERED IN. DRIVEN	MOISTURE (%)	DRY DENSITY (PCF)	Qu (TSF)	% PASSING #200 SIEVE	REMARKS/ ADDITIONAL DATA	
	ACE ELEV.: 300.0 ft. 4" Topsoil	_	299.7		шги			==				*	E 4 D	
	Loose to medium dens FINE SAND (SM) with	e brown and gray SILTY mica			2-3-5 N=8	1	SS	8/18 44%	16					
					4-6-6 N=12	2	SS	14/18 78%	18					
				_ 	2-2-3 N=5	3	SS	12/18 67%	13			22		
10.0			290.0		2-4-10 N=14	4	SS	15/18 83%	14					
WA WL WL	End of Boring @ 10 ft													
WA	ITER LEVEL OBSERVATIO	NS	AB C	onsu	Itants, In	IC.	STA	RTED:	11/20	0/12	FINIS	SHED:	11/20/12	
WL	Dry @ D	rilling	9450	Annap	olis Road		DRIL	L CO.:	P	ABC	DRIL	L RIG:	B-61	
WL	Dry, caved in 6.5 ft @ 0	Hrs			20706 306-3091		DRIL	LER:		PS	ASS"	T DRILLI	ER:	
WL	Dry, caved in 6.5 ft After	24 Hrs	Phone: 301-306-3091 Fax: 301-306-3092					DRILLER: PS  LOGGED BY:				ASS'T DRILLER:  APPROVED:		



**DEPTH** 

6.0





BOREHOLE NO.

B-51

AB Consultants, Inc. 9450 Annapolis Road Lanham, MD 20706 Phone: 301-306-3091 Fax: 301-306-3092

### **GRAIN SIZE DISTRIBUTION**


CLIENT: McCormick Taylor, Inc PROJECT NO.: 10-368.01

PROJECT: MO County Task Order # 13 Subtask B (Phase 3)

SITE:

**DEPTH** 

6.0





BOREHOLE NO.

B-53


AB Consultants, Inc. 9450 Annapolis Road Lanham, MD 20706 Phone: 301-306-3091 Fax: 301-306-3092

### **GRAIN SIZE DISTRIBUTION**

CLIENT: McCormick Taylor, Inc PROJECT NO.: 10-368.01

PROJECT: MO County Task Order # 13 Subtask B (Phase 3)

SITE:





### **GRAIN SIZE DISTRIBUTION**


CLIENT: McCormick Taylor, Inc PROJECT NO.: 10-368.01

PROJECT: MO County Task Order # 13 Subtask B (Phase 3)

SITE:

**DEPTH** 

3.5





BOREHOLE NO.

B-57

AB Consultants, Inc. 9450 Annapolis Road Lanham, MD 20706 Phone: 301-306-3091 Fax: 301-306-3092

### **GRAIN SIZE DISTRIBUTION**


CLIENT: McCormick Taylor, Inc PROJECT NO.: 10-368.01

PROJECT: MO County Task Order # 13 Subtask B (Phase 3)

SITE:

**DEPTH** 

6.0





BOREHOLE NO.

B-59


AB Consultants, Inc. 9450 Annapolis Road Lanham, MD 20706 Phone: 301-306-3091 Fax: 301-306-3092

### **GRAIN SIZE DISTRIBUTION**

CLIENT: McCormick Taylor, Inc PROJECT NO.: 10-368.01

PROJECT: MO County Task Order # 13 Subtask B (Phase 3)

SITE:






### **GRAIN SIZE DISTRIBUTION**

CLIENT: McCormick Taylor, Inc PROJECT NO.: 10-368.01

PROJECT: MO County Task Order # 13 Subtask B (Phase 3)

SITE:






### **GRAIN SIZE DISTRIBUTION**

CLIENT: McCormick Taylor, Inc PROJECT NO.: 10-368.01

PROJECT: MO County Task Order # 13 Subtask B (Phase 3)

SITE:





### **GRAIN SIZE DISTRIBUTION**


CLIENT: McCormick Taylor, Inc PROJECT NO.: 10-368.01

PROJECT: MO County Task Order # 13 Subtask B (Phase 3)

SITE:

**DEPTH** 

3.5





BOREHOLE NO.

**B-67** 


AB Consultants, Inc. 9450 Annapolis Road Lanham, MD 20706 Phone: 301-306-3091 Fax: 301-306-3092

### **GRAIN SIZE DISTRIBUTION**

CLIENT: McCormick Taylor, Inc PROJECT NO.: 10-368.01

PROJECT: MO County Task Order # 13 Subtask B (Phase 3)

SITE:






### **GRAIN SIZE DISTRIBUTION**

CLIENT: McCormick Taylor, Inc PROJECT NO.: 10-368.01

PROJECT: MO County Task Order # 13 Subtask B (Phase 3)

SITE:






### **GRAIN SIZE DISTRIBUTION**

CLIENT: McCormick Taylor, Inc PROJECT NO.: 10-368.01

PROJECT: MO County Task Order # 13 Subtask B (Phase 3)

SITE:



JOB NO.: 10-368 **DRILLED BY:** DATE: 12/4/2012

PROJECT: Mont Co Task Order#13 Subtask B (Pha LOCATION:


**HOLE NO.:** B-51

**HOLE DEPTH:** 5.2 Feet **HOLE DIAMETER:** 8 Inch

12/4/2012 PRE-SOAK DATE:

**PIPE DIAMETER:** 5 Inch PVC **PIPE MATERIAL:** 

**TESTED BY:** ΑT 12/5/2012 **TESTED DATE:** 



PS

Pre-soak water remaining in the hole: Yes / No Depth: (from bottom) 0

	Time of Reading (Hr : Min)		Time Water Level (Below Escaped Reference		Drop in Level	Infiltration Rate
Initial	final	(min)	Initial	Final	(in.)	(in./hr)
7:44	8:44	60	46 9/16	47 14/16	1.300	1.30
8:44	9:44	60	44 14/16	46 15/16	2.060	2.06
9:45	10:44	59	45 10/16	47 3/16	1.560	1.59
10::45	11:45	60	45 10/16	47 4/16	1.680	1.68

NOTE: \* Reading accuracy to 1/16"

**Average of 4-hr Monitoring Period:** 1.66 in./hr **Recommended Infiltration Rate:** 1.70 in./hr Report Reviewed and Prepared By: KC

REMARKS:	
i	

**JOB NO.:** 10-368.01

PROJECT: Mont Co Task Order#13 Subtask B (Pha

LOCATION:

Measurements (in.)

PS

12/4/2012

HOLE NO.: B-52

HOLE DIAMETER: 5.4 Feet

HOLE DIAMETER: 8 Inch


**PRE-SOAK DATE:** 12/4/2012

PIPE DIAMETER: 5 Inch

PIPE MATERIAL: PVC

TESTED BY: AT

**TESTED DATE**: 12/5/2012



**DRILLED BY:** 

DATE:

Pre-soak water remaining in the hole: Yes / No Depth: (from bottom) 20 6/16

	Time of Reading (Hr : Min)		Time Water Level (Below Escaped Reference		Drop in Level	Infiltration Rate
Initial	final	(min)	Initial	Final	(in.)	(in./hr)
7:53	8:53	60	27 6/16	27 9/16	0.200	0.20
8:53	9:52	59	27 2/16	27 6/16	0.240	0.24
9:52	10:52	60	25 7/16	25 9/16	0.120	0.12
10:52	11:52	60	25 9/16	25 11/16	0.120	0.12

NOTE: \* Reading accuracy to 1/16"

Average of 4-hr Monitoring Period:

Recommended Infiltration Rate:

0.20 in./hr
Report Reviewed and Prepared By:

REMARKS:	

**JOB NO.**: 10-368.01

Mont Co Task Order#13 Subtask B (Pha

PROJECT: LOCATION:

DRILLED BY: PS

DATE: 12/4/2012

Measurements (in.)

HOLE NO.: B-53

 HOLE DEPTH:
 5.2
 Feet

 HOLE DIAMETER:
 8
 Inch

**PRE-SOAK DATE:** 12/4/2012

PIPE DIAMETER: 5 Inch
PIPE MATERIAL: PVC

 TESTED BY:
 AT

 TESTED DATE:
 12/5/2012

5 Inch

PVC

AT

12/5/2012

d<sub>2</sub>

49 7/16

d<sub>3</sup>

69 10/16</sub>

Pre-soak water remaining in the hole: Yes / No Depth: (from bottom) 20 3/16

	Time of Reading (Hr : Min)		ng Time Water Level (Below Escaped Reference		Drop in Level	Infiltration Rate
Initial	final	(min)	Initial	Final	(in.)	(in./hr)
8:01	9:00	59	26 8/16	27 1/16	0.540	0.55
9:00	10:00	60	26 8/16	27 1/16	0.540	0.54
10:02	11:02	60	26 6/16	27	0.600	0.60
11:03	12:03	60	24 13/16	25 6/16	0.560	0.56

NOTE: \* Reading accuracy to 1/16"

Average of 4-hr Monitoring Period: 0.56 in./hr
Recommended Infiltration Rate: 0.50 in./hr

Report Reviewed and Prepared By:

REMARKS:	

KC

**JOB NO.**: 10-368.01

Mont Co Task Order#13 Subtask B (Pha

DRILLED BY:

PS 12/3/2012

PROJECT: LOCATION:

HOLE NO.: B-54

HOLE DEPTH: 5.2 Feet


HOLE DIAMETER: 8 Inch

PRE-SOAK DATE: 12/3/2012

PIPE DIAMETER: 5 Inch

PIPE MATERIAL: PVC
TESTED BY: AT

**TESTED DATE**: 12/4/2012



DATE:

Pre-soak water remaining in the hole:

Yes / No

Depth: (from bottom)

10 6/16

	Time of Reading (Hr : Min)		Water Level (Below Reference		Drop in Level	Infiltration Rate
Initial	final	(min)	Initial	Final	(in.)	(in./hr)
8:05	9:06	61	37 3/16	38 6/16	1.200	1.18
9:06	10:05	59	36	37 3/16	1.200	1.22
10:06	11:06	60	34 13/16	35 15/16	1.140	1.14
11:06	12:06	60	35 15/16	37 2/16	1.200	1.20

NOTE: \* Reading accuracy to 1/16"

Average of 4-hr Monitoring Period: 1.19 in./hr
Recommended Infiltration Rate: 1.20 in./hr

Report Reviewed and Prepared By: KC

REMARKS:	

JOB NO.: 10-368.01

Mont Co Task Order#13 Subtask B (Pha

PROJECT: LOCATION: **DRILLED BY:** PS DATE: 12/4/2012


**HOLE NO.:** B-55

**HOLE DEPTH:** 5.3 Feet **HOLE DIAMETER:** 8 Inch

PRE-SOAK DATE: 12/4/2012

**PIPE DIAMETER:** Inch 5 PVC **PIPE MATERIAL:** ΑT **TESTED BY:** 

**TESTED DATE:** 12/5/2012



Pre-soak water remaining in the hole: Yes / No Depth: (from bottom) 18 8/16

	Time of Reading (Hr : Min)		<u> </u>		•	Drop in Level	Infiltration Rate
Initial	final	(min)	Initial	Final	(in.)	(in./hr)	
8:07	9:10	63	28 15/16	29 8/16	0.600	0.57	
9:11	10:11	60	27 6/16	27 12/16	0.360	0.36	
10:12	11:12	60	26 6/16	26 12/16	0.360	0.36	
11:12	12:10	58	26 12/16	27 4/16	0.460	0.48	

NOTE: \* Reading accuracy to 1/16"

**Average of 4-hr Monitoring Period:** 0.44 in./hr **Recommended Infiltration Rate:** 0.40 in./hr KC

Report Reviewed and Prepared By:

REMARKS:	

JOB NO.: 10-368.01

**PROJECT:** Mont Co Task Order#13 Subtask B (Pha

LOCATION:

**HOLE NO.:** 


B-56

**HOLE DEPTH:** 5.0 Feet **HOLE DIAMETER:** 8 Inch

PRE-SOAK DATE: 12/3/2012

**PIPE DIAMETER:** 5 Inch PVC **PIPE MATERIAL: TESTED BY:** ΑT

**TESTED DATE:** 12/4/2012



**DRILLED BY:** 

DATE:

PS

12/3/2012

16 15/16

Pre-soak water remaining in the hole: Yes / No Depth: (from bottom)

	Time of Reading (Hr : Min)		Water Level (Below Reference		Drop in Level	Infiltration Rate
Initial	final	(min)	Initial	Final	(in.)	(in./hr)
7:37	8:36	59	29 6/16	30	0.600	0.61
8:37	9:36	59	27 10/16	28 3/16	0.600	0.61
9:36	10:36	60	25 13/16	26 6/16	0.600	0.60
10:36	11:36	60	26 6/16	26 15/16	0.520	0.52

NOTE: \* Reading accuracy to 1/16"

**Average of 4-hr Monitoring Period:** 0.59 in./hr **Recommended Infiltration Rate:** 0.60 in./hr KC

Report Reviewed and Prepared By:

REMARKS:	

JOB NO.: 10-368.01

Mont Co Task Order#13 Subtask B (Pha

**DRILLED BY:** DATE:

PS 12/3/2012

**PROJECT:** LOCATION:

**TESTED DATE:** 


**HOLE NO.:** B-57

**HOLE DEPTH:** 5.4 Feet **HOLE DIAMETER:** 8 Inch

PRE-SOAK DATE: 12/3/2012

**PIPE DIAMETER:** 5 Inch PVC **PIPE MATERIAL:** 

**TESTED BY:** ΑT 12/4/2012



Pre-soak water remaining in the hole: Yes / No Depth: (from bottom) 7 1/16

	Time of Reading (Hr : Min)		·		Drop in Level	Infiltration Rate
Initial	final	(min)	Initial	Final	(in.)	(in./hr)
7:48	8:48	60	52 3/16	53 8/16	1.320	1.32
8:48	9:46	58	51	52 3/16	1.200	1.24
9:47	10:47	60	50 6/16	51 10/16	1.200	1.20
10:47	11:45	58	49 9/16	50 12/16	1.220	1.26

NOTE: \* Reading accuracy to 1/16"

**Average of 4-hr Monitoring Period:** 1.26 in./hr **Recommended Infiltration Rate:** 1.20 in./hr

Report Reviewed and Prepared By: KC

REMARKS:	

JOB NO.: 10-368.01 DRILLED BY:

PROJECT: Mont Co Task Order#13 Subtask B (Pha DATE:

PROJECT: Mont Co Task Order#13 Subtask B (Pha

12/4/2012

HOLE NO.: B-58

HOLE DEPTH: 5.3 Feet

HOLE DIAMETER: 8 Inch


**PRE-SOAK DATE:** 12/3/2012

**TESTED DATE:** 

PIPE DIAMETER: 5 Inch

PIPE MATERIAL: PVC

TESTED BY: AT



PS

12/3/2012

Pre-soak water remaining in the hole: Yes / No Depth: (from bottom) 7 15/16

	Time of Reading (Hr : Min)		Water Level (Below Reference		Drop in Level	Infiltration Rate
Initial	final	(min)	Initial	Final	(in.)	(in./hr)
7:56	8:55	59	50 8/16	51 12/16	1.200	1.22
8:56	9:54	58	48 12/16	49 13/16	1.080	1.12
9:54	10:54	60	47 10/16	48 13/16	1.200	1.20
10:54	11:55	61	48 13/16	50 1/16	1.200	1.18

NOTE: \* Reading accuracy to 1/16"

Average of 4-hr Monitoring Period:

Recommended Infiltration Rate:

1.18 in./hr

1.20 in./hr

Report Reviewed and Prepared By:

REMARKS:	

JOB NO.: 10-368.01

Mont Co Task Order#13 Subtask B (Pha

**PROJECT:** LOCATION: **DRILLED BY:** PS DATE: 12/4/2012

**HOLE NO.:** 


B-59 **HOLE DEPTH:** 5.2 Feet **HOLE DIAMETER:** 8 Inch

PRE-SOAK DATE:

12/4/2012

**PIPE DIAMETER:** 

5 Inch PVC **PIPE MATERIAL: TESTED BY:** ΑT 12/5/2012 **TESTED DATE:** 



Measurements (in.)

19

73 13/16

Pre-soak water remaining in the hole:

Yes / No

Depth: (from bottom)

7 9/16

81 6/16

	Time of Reading (Hr : Min)		Water Level (Below Reference		Drop in Level	Infiltration Rate
Initial	final	(min)	Initial	Final	(in.)	(in./hr)
8:13	9:15	62	50 4/16	51 8/16	1.200	1.16
9:16	10:16	60	48 13/16	50 1/16	1.200	1.20
10:16	11:15	59	48 8/16	49 9/16	1.080	1.10
11:15	12:15	60	48	49 1/16	1.080	1.08

NOTE: \* Reading accuracy to 1/16"

**Average of 4-hr Monitoring Period:** 1.13 in./hr **Recommended Infiltration Rate:** 1.10 in./hr

Report Reviewed and Prepared By:

KC

REMARKS:	

**JOB NO.:** 10-368.01

Mont Co Task Order#13 Subtask B (Pha

Inch

DRILLED BY:

DATE:

PS 12/3/2012

PROJECT: LOCATION:

HOLE NO.: B-60

HOLE DEPTH: 5.3 Feet


 HOLE DIAMETER:
 8
 Inch

 PRE-SOAK DATE:
 12/3/2012

PIPE DIAMETER: 5

PIPE MATERIAL: PVC
TESTED BY: AT

**TESTED DATE**: 12/4/2012



Pre-soak water remaining in the hole: Yes / No Depth: (from bottom) 9 15/16

	Reading Min)	Time Escaped	Water Level (Below Reference		Drop in Level	Infiltration Rate
Initial	final	(min)	Initial	Final	(in.)	(in./hr)
7:27	8:27	60	36	37 1/16	1.080	1.08
8:28	9:28	60	34 5/16	35 6/16	1.080	1.08
9:29	10:29	60	32 12/16	33 13/16	1.080	1.08
10:29	11:29	60	31 7/16	32 8/16	1.080	1.08
						-

NOTE: \* Reading accuracy to 1/16"

Average of 4-hr Monitoring Period: 1.08 in./hr
Recommended Infiltration Rate: 1.00 in./hr

Report Reviewed and Prepared By: KC

REMARKS:	

JOB NO.: 10-368.01 **DRILLED BY:** DATE: 11/30/2012

**PROJECT:** Mont Co Task Order#13 Subtask B (Pha LOCATION:

**HOLE NO.:** B-61


12/1/2012

**HOLE DEPTH:** 5.4 Feet **HOLE DIAMETER:** 8 Inch

11/30/2012 PRE-SOAK DATE:

**TESTED DATE:** 

**PIPE DIAMETER:** 5 Inch PVC **PIPE MATERIAL: TESTED BY:** ΑТ



PS

Measurements (in.)

Pre-soak water remaining in the hole: Yes / No Depth: (from bottom) 0

	me of Reading Time Water Level (Below (Hr : Min) Escaped Reference		Time of Reading (Hr : Min)		Drop in Level	Infiltration Rate
Initial	final	(min)	Initial	Final	(in.)	(in./hr)
9:27	10:28	61	46 13/16	50 1/16	3.240	3.19
10:30	11:30	60	46 3/16	48 13/16	2.600	2.60
11:31	12:31	60	46	48 8/16	2.500	2.50
12:32	1:33	61	45 2/16	47 13/16	2.700	2.66

NOTE: \* Reading accuracy to 1/16"

**Average of 4-hr Monitoring Period:** 2.74 in./hr **Recommended Infiltration Rate:** 2.70 in./hr Report Reviewed and Prepared By: KC

REMARKS:	

**JOB NO.**: 10-368.01

PROJECT: Mont Co Task Order#13 Subtask B (Pha

LOCATION:

DRILLED BY: PS

DATE: 11/30/2012

HOLE NO.: B-62

HOLE DEPTH: 4.7 Feet

HOLE DIAMETER: 8 Inch


PRE-SOAK DATE: 11/30/2012

PIPE DIAMETER: 5 Inch

PIPE MATERIAL: PVC

TESTED BY: AT

**TESTED DATE**: 12/1/2012



Pre-soak water remaining in the hole: Yes / No Depth: (from bottom) \_\_\_\_\_\_0

Time of Reading (Hr : Min)		Time Escaped	Water Level (Below Reference		Drop in Level	Infiltration Rate
Initial	final	(min)	Initial	Final	(in.)	(in./hr)
9:35	10:34	59	40 8/16	41 10/16	1.100	1.12
10:36	10:34	58	39 11/16	40 11/16	1.000	1.03
11:35	12:35	60	39	40 2/16	1.100	1.10
12:36	1:40	64	38 3/16	39 6/16	1.200	1.13

NOTE: \* Reading accuracy to 1/16"

Average of 4-hr Monitoring Period:

Recommended Infiltration Rate:

1.10 in./hr
Report Reviewed and Prepared By:

REMARKS:

JOB NO.: 10-368.01

Mont Co Task Order#13 Subtask B (Pha

PROJECT: LOCATION: **DRILLED BY:** PS DATE: 11/30/2012

**HOLE NO.:** 


B-63 4.9 Feet

**HOLE DEPTH: HOLE DIAMETER:** 8 Inch

11/30/2012 PRE-SOAK DATE:

**PIPE DIAMETER:** 5 Inch PVC **PIPE MATERIAL:** AT **TESTED BY:** 

**TESTED DATE:** 12/1/2012



Pre-soak water remaining in the hole: Yes / No Depth: (from bottom) 21

	Reading Min)	Time Escaped	Water Level (Below Reference		Drop in Level	Infiltration Rate
Initial	final	(min)	Initial	Final	(in.)	(in./hr)
9:41	10:40	59	24	24 3/16	0.200	0.20
10:41	11:40	59	23 5/16	23 10/16	0.300	0.31
11:41	12:40	59	22 11/16	23	0.300	0.31
12:41	1:42	61	23	23 5/16	0.300	0.30

NOTE: \* Reading accuracy to 1/16"

**REMARKS:** 

**Average of 4-hr Monitoring Period:** 0.28 in./hr **Recommended Infiltration Rate:** 0.30 in./hr KC

Report Reviewed and Prepared By:

JOB NO.: 10-368.01

PROJECT: Mont Co Task Order#13 Subtask B (Pha

LOCATION:

HOLE NO.: B-64

HOLE DEPTH: 5.0 Feet


HOLE DIAMETER: 8 Inch

**PRE-SOAK DATE**: 11/30/2012

PIPE DIAMETER: 5 Inch
PIPE MATERIAL: PVC

 TESTED BY:
 AT

 TESTED DATE:
 12/1/2012



**DRILLED BY:** 

DATE:

PS

11/30/2012

Pre-soak water remaining in the hole: Yes / No Depth: (from bottom) \_\_\_\_\_0

	Time of Reading (Hr : Min)		Water Level (Below Reference		Drop in Level	Infiltration Rate
Initial	final	(min)	Initial	Final	(in.)	(in./hr)
9:20	10:18	58	55	57 2/16	2.100	2.17
10:20	11:20	60	54 3/16	56 10/16	2.400	2.40
11:21	12:19	58	54 5/16	55 11/16	1.400	1.45
12:20	1:20	60	53 3/16	54 11/16	1.500	1.50

NOTE: \* Reading accuracy to 1/16"

Average of 4-hr Monitoring Period:

Recommended Infiltration Rate:

1.88 in./hr

in./hr

Report Reviewed and Prepared By:

REMARKS:	

KC

 JOB NO.:
 10-368.01
 DRILLED BY:
 PS

 PROJECT:
 Mont Co Task Order#13 Subtask B (Pha
 DATE:
 11/30/2012

LOCATION:

HOLE NO.: B-65

 HOLE DEPTH:
 5.0
 Feet

 HOLE DIAMETER:
 8
 Inch

 PRE-SOAK DATE:
 11/30/2012


11/00/2012

 PIPE DIAMETER:
 5
 Inch

 PIPE MATERIAL:
 PVC

 TESTED BY:
 AT

 TESTED DATE:
 12/1/2012



Pre-soak water remaining in the hole: Yes / No Depth: (from bottom) 0

	Reading Min)	Time Escaped	Water Level (Below Reference		Drop in Level	Infiltration Rate
Initial	final	(min)	Initial	Final	(in.)	(in./hr)
9:13	10:12	59	56 2/16	58 2/16	2.025	2.06
10:14	11:12	58	55 13/16	57 10/16	1.800	1.86
11:13	12:13	60	54 11/16	56 5/16	1.600	1.60
12:14	1:16	62	53 3/16	54 14/16	1.700	1.65

NOTE: \* Reading accuracy to 1/16"

Average of 4-hr Monitoring Period:

Recommended Infiltration Rate:

1.80 in./hr
Report Reviewed and Prepared By:

REMARKS:	

JOB NO.: 10-368.01

Mont Co Task Order#13 Subtask B (Pha

**PROJECT:** LOCATION: **DRILLED BY:** PS DATE: 11/30/2012


**HOLE NO.:** B-66

**HOLE DEPTH:** 4.6 Feet **HOLE DIAMETER:** 8 Inch

11/30/2012 PRE-SOAK DATE:

**PIPE DIAMETER:** 5 Inch PVC **PIPE MATERIAL: TESTED BY:** ΑT

**TESTED DATE:** 12/1/2012



Pre-soak water remaining in the hole: Yes / No Depth: (from bottom) 0

	me of Reading Time Water Level (Below (Hr : Min) Escaped Reference		Drop in Level	Infiltration Rate		
Initial	final	(min)	Initial	Final	(in.)	(in./hr)
9:02	10:06	64	40	41 13/16	1.800	1.69
10:06	11:02	56	39 6/16	40 5/16	0.900	0.96
11:03	12:04	61	38 10/16	39 10/16	1.000	0.98
12:05	1:06	61	37 6/16	38 6/16	1.000	0.98
	_		_			

NOTE: \* Reading accuracy to 1/16"

**REMARKS:** 

**Average of 4-hr Monitoring Period:** 1.15 in./hr **Recommended Infiltration Rate:** 1.00 in./hr KC

Report Reviewed and Prepared By:

	·	 	

JOB NO.: 10-368.01

Mont Co Task Order#13 Subtask B (Pha

**PROJECT:** LOCATION: **DRILLED BY:** PS DATE: 11/20/2012

**HOLE NO.:** 


B-67 5.5 Feet

**HOLE DEPTH: HOLE DIAMETER:** 8 Inch

11/20/2012 PRE-SOAK DATE:

**PIPE DIAMETER:** 

5 Inch PVC **PIPE MATERIAL: TESTED BY:** SP/FU **TESTED DATE:** 11/21/2012



Pre-soak water remaining in the hole:

Yes / No

Depth: (from bottom)

0

	Time of Reading (Hr : Min)		e Water Level (Below ped Reference		Drop in Level	Infiltration Rate
Initial	final	(min)	Initial	Final	(in.)	(in./hr)
10:50	11:50	60	52 11/16	54 4/16	1.560	1.56
11:51	12:51	60	52 3/16	53 14/16	1.680	1.68
12:52	1:52	60	52 11/16	54 6/16	1.680	1.68
1:53	2:53	60	51 15/16	53 6/16	1.440	1.44

NOTE: \* Reading accuracy to 1/16"

**Average of 4-hr Monitoring Period:** 1.59 in./hr **Recommended Infiltration Rate:** 1.60 in./hr

Report Reviewed and Prepared By:

REMARKS:	

KC

**DRILLED BY:** 

DATE:

PS

11/20/2012

Measurements (in.)

12

78

**JOB NO.:** 10-368.01

PROJECT: Mont Co Task Order#13 Subtask B (Pha

LOCATION:

ask Graciii 10 Gablask B (1 lie

HOLE NO.: B-68

HOLE DEPTH: 5.5 Feet

HOLE DIAMETER: 8 Inch

PRE-SOAK DATE: 11/20/2012

PIPE DIAMETER: 5 Inch

PIPE MATERIAL: PVC
TESTED BY: SP/FU

TESTED DATE: 11/21/20			/2012		d <sub>3</sub> ₩	78
Pre-soak water remaining in the hole: Yes / No Depth: (from bottom)0						
	Reading Min)	Time Escaped		vel (Below rence	Drop in Level	Infiltration Rate
Initial	final	(min)	Initial	Final	(in.)	(in./hr)
10:57	11:57	60	51	52 9/16	1.560	1.56
11:58	12:58	60	50 8/16	52 1/16	1.560	1.56
12:59	1:59	60	50 14/16	52 3/16	1.320	1.32
2:00	3:00	60	51 4/16	52 9/16	1.320	1.32

NOTE: \* Reading accuracy to 1/16"

Average of 4-hr Monitoring Period: 1.44 in./hr
Recommended Infiltration Rate: 1.40 in./hr

Report Reviewed and Prepared By: KC

REMARKS:	

JOB NO.: 10-368.01

PROJECT: Mont Co Task Order#13 Subtask B (Pha

LOCATION:

HOLE NO.: B-69

HOLE DEPTH: 5.4 Feet

HOLE DIAMETER: 8 Inch


PRE-SOAK DATE: 11/20/2012

PIPE DIAMETER: 5 Inch

PIPE MATERIAL: PVC

TESTED BY: SP/FU

TESTED DATE: 11/21/2012



**DRILLED BY:** 

DATE:

PS

11/20/2012

Pre-soak water remaining in the hole: Yes / No Depth: (from bottom) \_\_\_\_\_\_0

	Reading Min)	Time Escaped	Water Level (Below Reference		Drop in Level	Infiltration Rate
Initial	final	(min)	Initial	Final	(in.)	(in./hr)
11:05	12:05	60	40 11/16	41 12/16	1.080	1.08
12:06	1:06	60	39 6/16	40 9/16	1.200	1.20
1:07	2:07	60	39 2/16	40 5/16	1.190	1.19
2:08	3:08	60	38 14/16	40 1/16	1.200	1.20

NOTE: \* Reading accuracy to 1/16"

Average of 4-hr Monitoring Period:

Recommended Infiltration Rate:

1.17 in./hr

in./hr

Report Reviewed and Prepared By: KC

REMARKS:	

**DRILLED BY:** 

DATE:

PS

11/20/2012

Measurements (in.)

45

70 8/16

**JOB NO.:** 10-368.01

PROJECT: Mont Co Task Order#13 Subtask B (Pha

LOCATION:

HOLE NO.: B-70

HOLE DIAMETER: 5.4 Feet

HOLE DIAMETER: 8 Inch

PRE-SOAK DATE: 11/20/2012

PIPE DIAMETER: 5 Inch

PIPE MATERIAL: PVC
TESTED BY: SP/FU

**TESTED DATE:** 11/21/2012

Pre-soak water remaining in the hole: Yes / No Depth: (from bottom) 25 8/16

	Reading Min)	Time Escaped	Water Level (Below Reference		Drop in Level	Infiltration Rate
Initial	final	(min)	Initial	Final	(in.)	(in./hr)
11:10	12:10	60	19 7/16	20 1/16	0.600	0.60
12:10	1:10	60	20 1/16	20 10/16	0.578	0.58
1:10	2:10	60	20 10/16	21 4/16	0.600	0.60
2:10	3:10	60	21 4/16	21 13/16	0.600	0.60

NOTE: \* Reading accuracy to 1/16"

Average of 4-hr Monitoring Period: 0.59 in./hr
Recommended Infiltration Rate: 0.60 in./hr

Report Reviewed and Prepared By: KC

REMARKS:	

 JOB NO.:
 10-368.01
 DRILLED BY:
 PS

 PROJECT:
 Mont Co Task Order#13 Subtask B (Pha
 DATE:
 11/20/2012

LOCATION:

HOLE NO.: B-71

HOLE DEPTH: 5.2 Feet


HOLE DIAMETER: 8 Inch
PRE-SOAK DATE: 11/20/2012

PIPE DIAMETER: 5 Inch

PIPE MATERIAL: PVC

TESTED BY: SP/FU

TESTED DATE: 11/21/2012



Measurements (in.)

Pre-soak water remaining in the hole: Yes / No Depth: (from bottom) 0

	Reading Min)	Time Escaped	Water Level (Below Reference		Drop in Level	Infiltration Rate
Initial	final	(min)	Initial	Final	(in.)	(in./hr)
11:17	12:17	60	42 4/16	44 4/16	2.040	2.04
12:18	1:18	60	42 8/16	44 3/16	1.680	1.68
1:19	2:19	60	42 15/16	44 10/16	1.680	1.68
2:20	3:12	52	42 4/16	43 11/16	1.440	1.66

NOTE: \* Reading accuracy to 1/16"

Average of 4-hr Monitoring Period:

Recommended Infiltration Rate:

1.70 in./hr
Report Reviewed and Prepared By:

REMARKS:	

**JOB NO.**: 10-368.01

PROJECT: Mont Co Task Order#13 Subtask B (Pha

LOCATION:

**HOLE NO.:** 

B-72

Inch

HOLE DEPTH: 5.4 Feet


HOLE DIAMETER: 8 Inch

PRE-SOAK DATE: 11/20/2012

PIPE DIAMETER: 5

PIPE MATERIAL: PVC
TESTED BY: SP/FU

**TESTED DATE**: 11/21/2012



**DRILLED BY:** 

DATE:

PS

11/20/2012

Pre-soak water remaining in the hole: Yes / No Depth: (from bottom) \_\_\_\_\_0

	Reading Min)	Time Escaped	Water Level (Below Reference		Drop in Level	Infiltration Rate
Initial	final	(min)	Initial	Final	(in.)	(in./hr)
11:23	12:23	60	42 12/16	44 6/16	1.680	1.68
12:24	1:24	60	42 6/16	43 13/16	1.440	1.44
1:25	2:25	60	42 13/16	44 4/16	1.440	1.44
2:26	3:26	60	41 14/16	43 5/16	1.440	1.44

NOTE: \* Reading accuracy to 1/16"

Average of 4-hr Monitoring Period: 1.50 in./hr
Recommended Infiltration Rate: 1.50 in./hr

Report Reviewed and Prepared By: KC

REMARKS:	